

Block Diagram

■ Location of Adjustment Parts




Fig. 14

Block Diagram





Fig. 15

Wiring Connection






Fig. 16




Fig. 16

Standard Schematic Diagram of TD-X401 (A)






Diagram of TD-X401 (Amplifier Circuit)

WI679 A





(Mecha Con





Diagram of TD-X401 (Mecha Control Circuit)



Circuit)






Fig. 18

P.C. Board Parts and Parts List







POWER Switch Board

POWER Cord Board

Main Amp. Board

Fig. 19